

CORNER RECORD


BK 56 PG 36
 Document Number CR-3414

APN No. 84B - 0310 - 32 - (Optional)

UNINCORPORATED

County of ALAMEDA, California

Brief Legal Description MONUMENT AT THE INTERSECTION OF ACORN & YUMA STREETS.



CORNER TYPE

Government Corner ☐ Control ☐
 Meander ☐ Property ☐
 Rancho ☐ Other ☐
 Date of Survey 2008

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

In compliance with Section 8771 of the Professional Land Surveyors' Act, this corner record is being filed to ESTABLISH _____ / REESTABLISH X the position of an existing monument PRIOR _____ / SUBSEQUENT X to street or highway reconstruction. (Use this portion only when applicable.)


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: THE MONUMENT DESCRIBED BELOW WAS REESTABLISHED BY RECORD INFORMATION ON TRACT MAPS 1463 AND 2857. SEE DRAWING ON NEXT PAGE.

A description of the physical condition of the monument as found and as set or reset: A STANDARD TRACT MONUMENT IN A MONUMENT WELL WAS DESTROYED DUE TO STORM SEWER CONSTRUCTION. THE MONUMENT WAS AT THE INTERSECTION OF ACORN AND YUMA STREETS.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 6/23/ 2008.

Signed Gregory Donald Hollfelder L.S. or R.C.E. Number 5918



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 6-23- 2008 and examined and filed 11-17-2013

Signed David Penland Title County Surveyor



County Surveyor's Comment _____

